



STRANICA S VRATIMA	A (mm)	C (mm)
100	970 - 1020	360
110	1070 - 1120	410
115	1120 - 1170	410
120	1170 - 1220	460
130	1270 - 1320	510
140	1370 - 1420	560
150	1470 - 1520	610
160	1570 - 1620	610
170	1670 - 1720	610
180	1770 - 1820	610